

TEST REPORT

CUSTOMER I.D.: 1541-94D
CUSTOMER NAME: Doerken Corp.

Date: February 25, 2016

ADDRESS: 11200 Cedar Knoll Dr.
Grass Lake, MI 49240

SAMPLES: 10 Samples

Mandrel Set 2: Delta-Protekt KL 120 and Delta-Seal HC Black

DATE RECEIVED: 12/16/15

PURCHASE ORDER: 205494

CONDITION AS RECEIVED: Good


Cyclic Corrosion per Ford CETP 00.00-L-467 200903

Start Date: 12/21/15

Duration: 4 Weeks to Date

Sample ID	Result
11	No visible corrosion at any weekly interval.
12	No visible corrosion at any weekly interval.
13	No visible corrosion at any weekly interval.
14	No visible corrosion at any weekly interval.
15	No visible corrosion at any weekly interval.
16	No visible corrosion at any weekly interval.
17	No visible corrosion at any weekly interval.
18	No visible corrosion at any weekly interval.
19	No visible corrosion at any weekly interval.
20	No visible corrosion at any weekly interval.

These testing results apply only to the samples submitted.



Christa Lammers
Laboratory Manager

2/25/16

Date

Thank you for your business.